



# Instructions for use

---

## **Product: Surface Cleaning Strips with Glycerine and Oxalic Acid ANEL**

Ref.: AN60551 Surface Cleaning Strips with Glycerine and Oxalic Acid ANEL  
Wide (40X400mm) Pack of 30pcs

Ref.: AN60552 Surface Cleaning Strips with Glycerine and Oxalic Acid ANEL  
Slim (25x400mm) Pack of 40pcs

Ref.: AN60554 Surface Cleaning Strips with Glycerine and Oxalic Acid ANEL  
Slim (25x400mm) Pack of 20pcs

Ref.: AN60555 Surface Cleaning Strips with Glycerine and Oxalic Acid ANEL  
Wide (50X50mm) Pack of 10pcs

Ref.: AN60556 Surface Cleaning Strips with Glycerine and Oxalic Acid ANEL  
Wide (100X100mm) Pack of 10pcs

Ref.: AN60557 Surface Cleaning Strips with Glycerine and Oxalic Acid ANEL  
Wide (150X150mm) Pack of 10pcs

Ref.: AN60558 Surface Cleaning Strips with Glycerine and Oxalic Acid ANEL  
Wide (200X200mm) Pack Of 10pcs

## **A. Application:**

Surfaces made of stainless steel, porcelain, glass, polyesters, polyurethane, sanitary ware (basin, tiles, toilet sink) and non-porous surfaces in general.

### **CAUTION!!!**

Before general application, test on a small part of the surface to make sure the product does not corrode your material.

## **B. Application:**

1. use plastic gloves.
2. use the product in well-ventilated areas (during use, depending on the substances found on the applied surface, it may release gases harmful to health).
3. The surfaces to be cleaned should be at a temperature of 10 - 35°C.

## **C. How to use:**

After choosing the size of the cleaning tape according to the surface you want to clean, put on the gloves, protective glasses and protective mask, open the package with a cutter and remove from it the number required for cleaning.

Gently rub the surfaces and, depending on the type and amount of dirt, leave from 1 to 10 minutes so that the film created on the surface from the friction to act.

Remove the film with a damp cloth and then rinse with water.